

Simpro Dock 2 I/O Port

[illegible]

B2402FBA	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B2402CVA	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B2402CBA	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B1502CVA	0	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1502CGA	0	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1502CBA	0	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1500CEPEY	X ¹	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1500CEPE	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B1500CEAEY	X ¹	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1500CEAE	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B1500CBA	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B1402CVA	0	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1402CGA	0	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1402CBA	0	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1400CEPEY	X ¹	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1400CEPE	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B1400CEAEY	X ¹	0	0	0	0	0	0	0	0	0	X ²	0	0	0
B1400CEAE	0	0	0	0	0	0	0	0	0	0	0	0	0	0
B1400CBA	0	0	0	0	0	0	0	0	0	0	0	0	0	0

See the ASUS Simpro Dock for more information on our [website page](#).

* These specific ExpertBooks have higher power requirements, so the Simpro Dock 2 with 120W power delivery, is not recommended. If these docks are used, the notebook needs to be plugged in externally for optimal performance.

1 The dock's power button can be sync with the notebook's power button. Please check notebooks' specification for full details.

2 When connected to non-Thunderbolt or display out systems, Simpro Dock 2 will not retain its Thunderbolt or display out functionality.

This document was last updated on September 6, 2023.