



# E500 G5 (WS C246 PRO) MEUpdate tool SOP


1. Check BIOS version which should be 0904




2. Use EZ flash to update BIOS to 1003




3. Please put BIOS 1003.CAP in USB Flash and choose the file




4. After Updating the BIOS, please reboot and enter Win10 operating system




## 5. Please execute MEUpdateTool\_12.0.39.1431 in operating system




## 6. Execute MEUpdateTool.exe



## 7. Waiting for update



## 8. Reboot after the update is completed



9. Please check version in BIOS setting

BIOS : 1003

ME : 12.0.39.1431

